

**Introductory Report on site visit to Kendriya Vidyalay AFS Manauri, Prayagraj
on 15.03.2021**


1. On the request of the Principal Kendriya Vidyalay AFS Manauri, Prayagraj, a visit to Kendriya Vidyalay AFS Manauri, Prayagraj was made by undersigned on 15.03.2021. Mrs. Shalini Dixit, Principal Kendriya Vidyalay AFS Manauri, Prayagraj and other staff members of the school assisted in the visit.

2. During the visit school old and newly constructed annexe buildings were visited.


i. In the old single storeyed load bearing structure of school buildings, surface deterioration alongwith minor cracking on walls is seen, while the newly constructed annexe building is in good condition.

ii. Considering the present occupancy and utilization of buildings, the the old single storeyed load bearing structure buildings may be used with limited access to the roof.

However the buildings should be investigated in detail for residual strength/ robustness/durability so that appropriate repairs and retrofitting techniques may be selected for repairs and retrofitting of buildings.


R.C. Vaishya 30/07/2021
Professor

Dr. R. C. Vaishya
Professor
Department of Civil Engineering
M. S. Swaminathan National Institute of Technology
Kharagpur-721 004 (U.P.) India


L.K. Mishra 30/07/2021
Professor

Dr. L.K. Mishra, Professor and Head, Institute
Department of Civil Engineering
M. S. Swaminathan National Institute of Technology
Kharagpur-721 004 (U.P.) India